

QUARTERLY TOWER INSPECTION

ASR: 1258601

ASR: 1018320

INSPECTION	FINDING	INITIAL
PAINT	OK	EB
LIGHTS	OK	EB
LIGHTING OUTAGE ALARM SYSTEM	OK	EB
GUY WIRES	OK	EB
FENCE	OK	EB

4/11/17:

SIDE MARKERS PERMANENTLY EXTINGUISHED PER:

FAA Aeronautical Study No. 2016-ACE-4941-OE

FAA Aeronautical Study No. 2016-ACE-4942-OE

(FAA Advisory Circular 70/7460-1, L Change 1 , Obstruction Marking and Lighting, paint/red lights

- Chapters 3(Marked),4,5(Red),&12)

X  07/01/17

Edwin Brand

Chief Operator, Honey Creek Broadcasting, LLC

QUARTERLY TOWER INSPECTION

ASR: 1258601

ASR: 1018320

INSPECTION	FINDING	INITIAL
PAINT	OK	EB
LIGHTS	OK	EB
LIGHTING OUTAGE ALARM SYSTEM	OK	EB
GUY WIRES	OK	EB
FENCE	OK	EB

X  10/01/17

Edwin Brand
Chief Operator, Honey Creek Broadcasting, LLC

QUARTERLY TOWER INSPECTION

ASR: 1258601

ASR: 1018320

INSPECTION	FINDING	INITIAL
PAIN	OK	EB
LIGHTS	OK	EB
LIGHTING OUTAGE ALARM SYSTEM	OK	EB
GUY WIRES	OK	EB
FENCE	OK	EB

LIGHT OUTAGE AND NOTAM INFO (0E9 – CORYDON):

!FOD 10/055 0E9 OBST TOWER LGT (ASR 1258601) 405323.50N0930129.80W (12.7NM NE 0E9) 1598.8FT (602.7FT AGL) OUT OF SERVICE
1710100359-1710172359

!FOD 10/095 0E9 OBST TOWER LGT (ASR 1258601) 405323.50N0930129.80W (12.7NM NE 0E9) 1598.8FT (602.7FT AGL) OUT OF SERVICE
1710160146-1710310146

!FOD 10/095 0E9 OBST TOWER LGT (ASR 1258601) IN SERVICE 1710301200

X:  01/04/18

EDWIN BRAND
CHIEF OPERATOR, HONEY CREEK BROADCASTING, LLC