

QUARTERLY TOWER INSPECTION

ASR: 1258601

ASR: 1018320

INSPECTION	FINDING	INITIAL
PAIN	OK	EB
LIGHTS	OK	EB
LIGHTING OUTAGE ALARM SYSTEM	OK	EB
GUY WIRES	OK	EB
FENCE	OK	EB

09/20/19: 1018320 - 12-bay antenna / heliax removed. 2-bay antenna moved to 500' level. P&T to original spec. NTC-Gordon.

X:  10/01/2019

EDWIN BRAND
CHIEF OPERATOR, HONEY CREEK BROADCASTING, LLC